

## SURF BAY LEISURE AFTERSALES WORKSHEET

**I AUTHORISE SURF BAY LEISURE TO ENTER THE CARAVAN LISTED BELOW:**

**SIGNATURE----- DATE-----**

**POSITION-----**

WORK CODE: LOG NO: SWIFT-8571 MAKE: Swift MODEL: Moselle Lodge SIZE: 40x13 SERIAL NO: 018849h STOCK NO: 31217 Assigned to Ellie W	ADDRESS: (754) <span style="color: blue;">(WAS MARLBOR)</span> Seven Bays Park St Meryn Padstowe PL28 8QA  PITCH NO: ..  TEL:
--	---

**Problem**

PDI reports a loose cover strip on the wall board in the lounge behind the picture – Please re-affix the joining strip on the wallboard ✓

Notes: ALSO ASKED TO REPORT SCRATCH TO WALL UNIT (IN TWIN BED) - PHOTO TAKEN  
ALSO COULDN'T (GIVE) WILL NOT LIGHT - TRY TO ADJUST ALSO USED

**Details of Work Done**

ALSO DAMAGE TO BLOWN LOUNGE MIRROR

ARRIVAL TIME	4.15
DEPARTURE TIME	5.15

DATE:	FITTER:
I AM HAPPY WITH THE WORK CARRIED OUT TODAY BY SURF BAY LEISURE	
PARK/CUSTOMER SIGNATURE:	

MATERIALS USED	NOTES